



RO-LEAK

No. R08730516

dated: 01/18

Item no.	Description	Article no.	Quantity
---	Charger Roleak	1500002899	1
1	Spare sensor Roleak	87309	1
2	Spare battery Roleak	1500002886	1

IMPORTANT! To assure safety and reliability, repairs, maintenance and adjustment must be preformed by ROTHENBERGER Kelkheim or authorized Service-Centers. Always use Original-Service-Parts. Order your accessories and spare parts from your specialist retailer or using RoService+ online.

Tel. +49 6195 - 800 **8200**

Fax: +49 6195 - 800 **7491**

 service@rothenberger.com