



TUBE BENDER
No. 24130_24010

dated: 08/17

| Item no. | Description | Article no. | Old article no. | Quantity |
|----------|-------------------------|-------------|-----------------|----------|
| 3 | Slidder | 766000300 | 7660003 | 1 |
| 19 | Set of guides compl. | 24049 | 24049 | 1 |
| 13 | Trigger | 766000500 | 7660005 | 1 |
| 6 | Rocker | 766001100 | 7660011 | 1 |
| 18 | Guide former compl. | 24048 | 24048 | 1 |
| 5 | Spring | 753001900 | 7530019 | 1 |
| 12 | Trigger spring | R8242700 | 82427 | 1 |
| 20 | Tension spring for rack | 766000400 | | 1 |
| 8 | Pulling spring | 766001000 | - | 1 |

IMPORTANT! To assure safety and reliability, repairs, maintenance and adjustment must be performed by ROTHENBERGER Kelkheim or authorized Service-Centers. Always use Original-Service-Parts. Order your accessories and spare parts from your specialist retailer or using our Service After Sales hotline

Tel. +49 6195 - 800 **8200**

Fax: +49 6195 - 800 **7491**

 service@rothenberger.com